

Systembilder



	Bestellbezeichnung Ordering code	h_1	b	l_1	l_2	w	T_{max}	D_{Start}	D_{min}	Schneideinsatz Inserts
CGAC...F...D... 	CGACR/L 2525 M3 F10.0 D30	25	25	150	18	3,0	10	35	30	FD LCMR...TM FD LCMN...
	CGACR/L 2525 M3 F10.0 D40	25	25	150	18	3,0	10	50	40	ED LC.R...TM *) ED LCMN... *)
	CGACR/L 2525 M3 F15.0 D50	25	25	150	18	3,0	15	60	50	
	CGACR/L 2525 M3 F15.0 D60	25	25	150	18	3,0	15	85	60	
	CGACR/L 2525 M4 F12.0 D30	25	25	150	18	4,0	12	40	30	
	CGACR/L 2525 M4 F15.0 D40	25	25	150	18	4,0	15	50	40	
	CGACR/L 2525 M4 F15.0 D50	25	25	150	18	4,0	15	60	50	
	CGACR/L 2525 M4 F15.0 D60	25	25	150	18	4,0	15	85	60	
	CGACR/L 2525 M6 F20.0 D60	25	25	150	22	6,0	20	85	60	
	CGACR/L 2525 M6 F20.0 D85	25	25	150	22	6,0	20	150	85	
	CGACR/L 2525 M6 F20.0 D150	25	25	150	22	6,0	20	250	150	

Ersatzteile Spare parts	Bestellbezeichnung Ordering code		
WSP Breite Size of insert	Schraube Screw	Schlüssel Key	SW AF
3	M5x16 DIN912	V01-A0040	4
4	M5x16 DIN912	V01-A0040	4
6	M6x25 DIN912	V01-A0050	5

*) $D_{min} = 60 \text{ mm}$

Passende Wendeplatten

Suitable inserts

FD LC...TM	ED LC...TM				

Seite Page
26

Seiten Pages
23, 24

Bestellbeispiel Order example: 1 Stück off CGACR 2525 M4 F12.0 D30